




**Fig. 1a**  
(PRIOR ART)




**Fig. 1b**  
(PRIOR ART)




**Fig. 2a**  
(PRIOR ART)




**Fig. 2b**  
(PRIOR ART)





**Fig. 2c**  
(PRIOR ART)





**Fig. 3**  
(PRIOR ART)




**Fig. 4**






$$H_X = 0$$

**Fig. 8a**




$$H_X = 0.25H_C$$

**Fig. 8b**




$$H_X = 0.50H_C$$


**Fig. 8c**




**Fig. 9a**




**Fig. 9b**



**Fig. 10a**



**Fig. 10b**




**Fig. 10c**



**Fig. 10d**





**Fig. 11**